

FIG. 1




FIG. 2




FIG. 3




FIG. 4a




FIG. 4b





FIG. 5

Chart: Grain Size (diameter)
Edge grains excluded from analysis



Grain Size distribution and data - Sample Ta A 1050

FIG. 6






Chart: Grain Size (diameter)
Edge grains excluded from analysis



Average Number 21.9237
Area 45.7317


Grain Size distribution and data - Sample Ta U 1100

FIG. 7




$$\frac{F}{G} \infty$$

Chart: Grain Size (diameter)
Edge grains excluded from analysis



Average
Number 9.59034
Area 15.3075

Grain Size distribution and data - Sample Nb u 1100

FIG. 9